CERTIFICATE OF COMPLIANCE

Certificate Number 20170921-E481373

Report Reference E481373-20161012

Issue Date 2017-SEPTEMBER-21

Issued to: RITTAL GMBH & CO. KG

AUF DEM STUETZELBERG 35745 HERBORN, GERMANY

This is to certify that Wire Connectors and Soldering Lugs - Component

representative samples of See Addendum Page For Models

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 486A-486B - Wire Connectors

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

The UL Recognized Component Mark generally consists of the manufacturer's identification and catalog number, model number or other product designation as specified under "Marking" for the particular Recognition as published in the appropriate UL Directory. As a supplementary means of identifying products that have been produced under UL's Component Recognition Program, UL's Recognized Component Mark: May be used in conjunction with the required Recognized Marks. The Recognized Component Mark is required when specified in the UL Directory preceding the recognitions or under "Markings" for the individual recognitions.

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.

Bandy Director North A

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



CERTIFICATE OF COMPLIANCE

Certificate Number 20170921-E481373

Report Reference E481373-20161012

Issue Date 2017-SEPTEMBER-21

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

```
Models 4050.751, 4050.752, 4050.753, 4050.754, 4050.755, 4050.756, 4050.757,
4050.758, 4050.759, 4050.760, 4050.761, 4050.762, 4050.763, 4050.764, 4050.765,
4050.766, 4050.767, 4050.768, 4050.769, 4050.770, 4050.771, 4050.772, 4050.773,
4050.774, 4050.775, 4050.776, 4050.777, 4050.778, 4050.734, 4050.779, 4050.780,
4050.781, 4050.782, 4050.735, 4050.783, 4050.784, 4050.785, 4050.786, 4050.787,
4050.788. 4050.789. 4050.790. 4050.791. 4050.792. 4050.793. 4051.585. 4051.586.
4050.794, 4050.795, 4050.796, 4050.797, 4051.611, 4050.730, 4051.612, 4051.613,
4051.614, 4050.731, 4051.615, 4051.616, 4051.617, 4051.618, 4050.732, 4051.619,
4051.620, 4051.621, 4050.733, 4051.622, 4051.623, 4051.624, 4050.736, 4051.625,
4051.626, 4051.627, 4051.628, 4051.629, 4051.630, 4051.631, 4051.632, 4051.689,
4051.690, 4051.633, 4051.634, 4051.635, 4051.804, 4051.703, 4051.704, 4051.705,
4051.706, 4051.707, 4051.708, 4051.709, 4051.710, 4051.711, 4051.712, 4051.713,
4051.714, 4051.715, 4051.716, 4051.717, 4051.718, 4051.719, 4051.720, 4051.721,
4051.722, 4051.723, 4051.724, 4051.725, 4051.726, 4051.727, 4051.728, 4051.729,
4051.730, 4051.731, 4051.732, 4051.733, 4051.734, 4051.735, 4051.736, 4051.737,
4051.738. 4051.739. 4050.798. 4050.799. 4051.500. 4051.501. 4051.502. 4051.503.
4051.504, 4051.505, 4051.506, 4051.507, 4051.508, 4051.509, 4051.510, 4051.511,
4051.512, 4051.513, 4051.514, 4051.515, 4051.516, 4051.517, 4051.518, 4051.519,
4051.520, 4051.521, 4051.522, 4051.523, 4051.524, 4051.525, 4050.741, 4051.526,
4051.527, 4051.528, 4051.529, 4051.636, 4051.637, 4051.638, 4050.737, 4051.639,
4051.640, 4051.641, 4050.738, 4051.642, 4051.643, 4051.644, 4050.739, 4051.645,
4051.646, 4051.647, 4050.740, 4051.648, 4051.649, 4051.740, 4051.741, 4051.742,
4051.743, 4051.744, 4051.745, 4051.746, 4051.747, 4051.748, 4051.749, 4051.750,
4051.751, 4051.752, 4051.753, 4051.754, 4051.755, 4051.756, 4051.757, 4051.758,
4051.759, 4051.760, 4051.761, 4051.762, 4051.763, 4051.764, 4051.765, 4051.530,
4051.531, 4051.532, 4051.533, 4051.534, 4051.535, 4051.536, 4051.537, 4051.538,
4051.539, 4051.540, 4051.541, 4051.542, 4051.543, 4051.544, 4051.545, 4051.546,
4051.547, 4051.548, 4051.549, 4051.550, 4051.551, 4051.552, 4051.553, 4051.554,
4051.555, 4051.650, 4051.651, 4051.652, 4051.653, 4051.654, 4051.655, 4051.656,
4051.657, 4051.658, 4051.659, 4051.660, 4051.661, 4051.662, 4051.663, 4051.664,
4051.665, 4051.666, 4051.667, 4051.668, 4051.669, 4051.766, 4051.767, 4051.768,
4051.769, 4051.770, 4051.771, 4051.772, 4051.773, 4051.774, 4051.775, 4051.776,
4051.777, 4051.778, 4051.779, 4051.780, 4051.556, 4051.557, 4051.558, 4051.559,
```



Bruce Mahrenholz, Director North American Certification Program

UL LLC





CERTIFICATE OF COMPLIANCE

Certificate Number 20170921-E481373

Report Reference E481373-20161012

Issue Date 2017-SEPTEMBER-21

```
\begin{array}{l} 4051.560,\ 4051.561,\ 4051.562,\ 4051.563,\ 4051.564,\ 4051.565,\ 4051.566,\ 4051.567,\ 4051.568,\ 4051.569,\ 4051.570,\ 4051.571,\ 4051.670,\ 4051.671,\ 4051.672,\ 4051.672,\ 4051.673,\ 4051.674,\ 4051.675,\ 4051.676,\ 4051.677,\ 4051.678,\ 4051.679,\ 4051.680,\ 4051.681,\ 4051.781,\ 4051.782,\ 4051.783,\ 4051.784,\ 4051.785,\ 4051.786,\ 4051.787,\ 4051.578,\ 4051.572,\ 4051.573,\ 4051.574,\ 4051.575,\ 4051.576,\ 4051.577,\ 4051.578,\ 4051.579,\ 4051.580,\ 4051.581,\ 4051.582,\ 4051.583,\ 4051.584,\ 4050.742,\ 4051.682,\ 4051.683,\ 4050.743,\ 4051.684,\ 4051.685,\ 4050.744,\ 4051.686,\ 4051.687,\ 4050.745,\ 4051.803,\ 4051.688,\ 4051.789,\ 4051.790,\ 4051.791,\ 4051.792,\ 4051.793,\ 4051.587,\ 4051.588,\ 4051.794,\ 4051.590,\ 4051.591,\ 4051.592,\ 4051.691,\ 4051.692,\ 4051.693,\ 4051.596,\ 4051.597,\ 4051.598,\ 4051.599,\ 4051.593,\ 4051.594,\ 4051.695,\ 4051.696,\ 4051.694,\ 4051.697,\ 4050.749,\ 4051.698,\ 4051.797,\ 4051.695,\ 4051.696,\ 4051.696,\ 4051.606,\ 4051.607,\ 4051.608,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051.609,\ 4051
```



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

