Certificate Number UL-US-L491171-14-72408102-1

Report Reference E491171-20180427

Date 12-May-2021

Issued to: RITTAL GmbH & Co. KG

Auf dem Stuetzelberg Herborn

Germany 35745

This is to certify that representative samples of

FTTA - Environmental-rated Accessories for Enclosures

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 50, 13th Ed., Issue Date: 2015-10-16, UL 50E, 2nd Ed.,

Issue Date: 2015-10-16

Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.







Certificate Number UL-US-L491171-14-72408102-1

Report Reference E491171-20180427

> **Date** 12-May-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
VX, followed by 8951.020, 8951.030, 8951.000,	Disconnector Hoods
8951.010, 8952.020, 8952.030, 8952.000, and	
8952.020, 8951.005 and 8952.005.	NULNULNULNULNU
Disconnector Hoods Special Order, VX YYYY.YYY,	Disconnector Hoods
where YYYY.YYY can be any number.	



Bruce Mahrenholz, Director North American Certification Program





Certificate Number UL-CA-L491171-34-72408102-1

Report Reference E491171-20180427

Date 12-May-2021

Issued to: RITTAL GmbH & Co. KG

Auf dem Stuetzelberg Herborn

Germany 35745

This is to certify that representative samples of

FTTA7 - Environmental-rated Accessories for Enclosures

Certified for Canada

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 NO. 94.1-15, 2nd Ed., Issue Date: 2015-10-16,

CSA C22.2 NO. 94.2-15, 2nd Ed., Issue Date: 2015-10-16

Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

(U)

Certificate Number UL-CA-L491171-34-72408102-1

Report Reference E491171-20180427

Date 12-May-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
VX, followed by 8951.020, 8951.030, 8951.000,	Disconnector Hoods
8951.010, 8952.020, 8952.030, 8952.000, and	
8952.020, 8951.005 and 8952.005.	
Disconnector Hoods Special Order, VX YYYY.YYY,	Disconnector Hoods
where YYYY.YYY can be any number.	

Bamere

Bruce Mahrenholz, Director North American Certification Program

JL LLC

(U)

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/.