Certificate Number Report Reference Issue Date 20201005-E518138 E518138-20201005 2020-OCTOBER-15

Issued to: RITTAL GmbH & Co. KG Auf dem Stuetzelberg Herborn, 35745 DE

This certificate confirms that representative samples of

atBARE AND COVERED FERRULESofSee addendum page for models

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:Bare and Covered Ferrules, UL 486F, First Edition
CSA C22.2 No. 291-14, First EditionAdditional Information:See the UL Online Certifications Directory at
https://iq.ulprospector.com
for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Ba Mall

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Issue Date 20201005-E518138 E518138-20201005 2020-OCTOBER-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Covered Ferrule

AS 4050.759, AS 4050.760, AS 4050.761, AS 4050.762, AS 4050.763, AS 4050.764, AS 4050.765 AS 4050.766, AS 4050.767, AS 4050.768, AS 4050.769, AS 4050.770, AS 4050.771, AS 4050.772 AS 4050.773, AS 4050.774, AS 4050.775, AS 4050.776, AS 4050.777, AS 4051.611, AS 4050.730 AS 4051.612, AS 4051.613, AS 4051.614, AS 4050.731, AS 4051.615, AS 4051.616, AS 4051.617 AS 4051.618, AS 4050.732, AS 4051.619, AS 4051.620, AS 4051.621, AS 4050.733, AS 4051.622 AS 4051.623, AS 4051.624, AS 4051.720, AS 4051.721, AS 4051.715, AS 4051.716, AS 4051.717 AS 4051.718, AS 405.1719, AS 4050.778, AS 4050.734, AS 4050.779, AS 4050.780, AS 4050.781 AS 4050.782, AS 4050.735, AS 4050.783, AS 4050.784, AS 4050.778, AS 4050.734, AS 4050.779 AS 4050.780, AS 4050.781, AS 4050.782, AS 4050.735, AS 4050.783, AS 4050.784, AS 4051.722 AS 4051.723, AS 4051.724, AS 4051.725, AS 4051.726, AS 4051.727, AS 4051.728, AS 4051.729 AS 4051.730, AS 4050.785, AS 4050.786, AS 4050.787, AS 4050.788, AS 4050.789, AS 4050.790 AS 4050.791, AS 4050.792, AS 4050.793, AS 4050.794, AS 4050.795, AS 4050.796, AS 4050.797 AS 4050.736, AS 4051.625, AS 4051.626, AS 4051.627, AS 4051.628, AS 4051.629, AS 4051.630 AS 4051.631, AS 4051.632, AS 4051.633, AS 051.634, AS 4051.635, AS 4051.804, AS 4051.731 AS 4051.732, AS 4051.733, AS 4051.734, AS 4051.735, AS 4051.736, AS 4051.737, AS 4051.738 AS 4051.739, AS 4050.794, AS 4050.795, AS 4050.796, AS 4050.797, AS 4051.506, AS 4051507 AS 4051.508, AS 4051.509, AS 4051.510, AS 4051.511, AS 4051.512, AS 4051.513, AS 4051.514 AS 4051.515, AS 4051.516, AS 4051.517, AS 4051.518, AS 4051.519, AS 4051.520, AS 4051.521 AS 4051.522, AS 4051.523, AS 4051.524, AS 4051.525, AS 4050.741, AS 4051.526, AS 405.1527 AS 4051.528, AS 4051.529, AS 4051.636, AS 405.1637, AS 405.1638, AS 4050.737, AS 4051.752 AS 4051.753, AS 4051.754, AS 4051.755, AS 4051.642, AS 4051.643, AS 4051.644, AS 4050.739 AS 4051.645, AS 4051.646, AS 4051.647, AS 4050.740, AS 4051.756, AS 4051.757, AS 4051.758 AS 4051.759, AS 4051.760, AS 4051.761, AS 4051.762, AS 4051.763, AS 4051.764, AS 4051.765 AS 4051.530, AS 4051.531, AS 4051.532, AS 4051.533, AS 4051.534, AS 4051.535, AS 4051.552 AS 4051.553, AS 4051.554, AS 4051.555, AS 4051.650, AS 4051.651, AS 4051.652, AS 4051.653 AS 4051.654, AS 4051.766, AS 4051.767, AS 4051.655, AS 4051.656, AS 4051.657, AS 4051.658 AS 4051.659, AS 4051.660, AS 4051.661, AS 4051.662, AS 4051.663, AS 4051.664, AS 4051.665 AS 4051.666, AS 4051.667, AS 4051.668, AS 4051.669, AS 4051.768, AS 4051.769, AS 4051.770 AS 4051.771, AS 4051.772, AS 4051.773, AS 4051.774, AS 4051.775, AS 4051.776, AS 4051.777 AS 4051.778, AS 4051.779, AS 4051.780, AS 4051.556, AS 4051.557, AS 4051.558, AS 4051.559 AS 4051.560, AS 4051.561, AS 4051.562, AS 4051.563, AS 4051.564, AS 4051.565, AS 4051.566 AS 4051.567, AS 4051.568, AS 4051.569, AS 4051.570, AS 4051.571, AS 4051.670, AS 4051.671 AS 4051.672, AS 4051.673, AS 4051.674, AS 4051.675, AS 4051.676, AS 4051.677, AS 4051.678 AS 4051.679. AS 4051.567. AS 4051.568. AS 4051.680. AS 4051.681. AS 4051.781. AS 4051.782 AS 4051.783, AS 4051.784, AS 4051.785

Barnally

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Issue Date 20201005-E518138 E518138-20201005 2020-OCTOBER-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Covered Ferrule

AS 4051.786, AS 4051.787, AS 4051.788, AS 4051.574, AS 4051.575, AS 4051.576, AS 4051.577 AS 4051.578, AS 4051.579, AS 4051.580, AS 4051.581, AS 4051.582, AS 4051.583, AS 4051.584 AS 4051.585, AS 4051.586, AS 4050.742, AS 4051.682, AS 4051.683, AS 4050.743, AS 4051.684 AS 4051.685, AS 4050.744, AS 4051.686, AS 4051.687, AS 4050.745, AS 4051.803, AS 4051.688 AS 4051.689, AS 4050.744, AS 4051.791, AS 4051.792, AS 4051.793, AS 4051.589, AS 4051.590 AS 4051.591, AS 4051.592, AS 4051.691, AS 4051.692, AS 4051.693, AS 4051.694, AS 4051.593 AS 4051.796, AS 4051.597, AS 4051.598, AS 4051.692, AS 4051.600, AS 4051.601, AS 4051.602 AS 4051.603, AS 4051.604, AS 4050.750, AS 4051.605, AS 4050.746, AS 4051.695, AS 4051.602 AS 4051.696, AS 4050.748, AS 4050.750, AS 4051.605, AS 4050.746, AS 4051.695, AS 4051.798 AS 4051.696, AS 4050.748, AS 4051.597, AS 4051.539, AS 4051.541, AS 4051.537, AS 4051.542 AS 4051.538, AS 4051.543, AS 4051.539, AS 4051.536, AS 4051.605, AS 4051.541, AS 4051.547, AS 4051.544 AS 4051.538, AS 4051.543, AS 4051.550, AS 4050.750, AS 4051.605, AS 4051.541, AS 4051.548, AS 4051.544 AS 4051.549, AS 4051.543, AS 4051.550, AS 4050.750, AS 4051.605, AS 4051.541, AS 4051.547, AS 4051.544 AS 4051.549, AS 4051.545, AS 4051.550, AS 4051.546, AS 4051.551, AS 4051.547, AS 4051.549 AS 4051.549, AS 4051.545, AS 4051.550, AS 4051.546, AS 4051.551, AS 4051.547, AS 4051.549 AS 4051.800, AS 4051.606, AS 4051.607, AS 4051.608, AS 4051.609, AS 4051.640, AS 4051.699 AS 4051.700, AS 4051.701, AS 4051.702, AS 4051.801, AS 4051.802

Barhely

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Issue Date 20201005-E518138 E518138-20201005 2020-OCTOBER-15

Barnelly

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/