


Enclosures

Support arm system CP-S

Enclosure attachment, tilting, top mounting

Catalogue 33, page 151


IW 6902.670



Enclosure attachment CP-S

Catalogue 33, page 151


CP 6501.070



Enclosure coupling CP-S

For support arm connection CP-S, round Catalogue 33, page 151


CP 6501.050



Enclosure coupling CP-S

For support arm connection CP-L $\square$ 120 x 65 mm Catalogue 33, page 151


CP 6501.130




Angle coupling 90° CP-S

Catalogue 33, page 151

CP 6501.120




Possible mounting cut-outs of enclosures



Version c) for quick/one-man assembly

Support section CP-S

Catalogue 33, page 151



A mm	Model No. CP
500	6501.000
1000	6501.020

$A_{min.} = 100 \text{ mm}$
 $A_{max.} = 2000 \text{ mm}$


Enclosures

Support arm system CP-S

Angle piece 90° CP-S

Catalogue 33, page 151


CP 6501.140




Top-mounted joint CP-S

Catalogue 33, page 151

CP 6501.160




Mounting cut-out




Wall-mounted hinge CP-S

Catalogue 33, page 151

CP 6501.150



Mounting cut-out 90°




- 1** Locking screw
- 2** Adjusting screw
- 3** Screw for adjusting rotatability
- 4** Removable plate

Wall/base mounting CP-S


Catalogue 33, page 151

CP 6501.110



- 1** Adjusting screw

View A



Mounting cut-out

