


Rittal – The System.

Faster – better – everywhere.



SK 3398.342 Invertor

State: 4.6.2026 (Source: rittal.com/sk-sk)

ENCLOSURES

POWER DISTRIBUTION

CLIMATE CONTROL

IT INFRASTRUCTURE

SOFTWARE & SERVICES

FRIEDHELM LOH GROUP



SK 3398.342 - Invertor

Náhradný diel

Features

Obj. č.	SK 3398.342
---------	-------------

Vhodný pre obj. č.	3186630
	3186930
	3187630
	3187930
	3312810
	3320200

Balenie	1 pc(s).
---------	----------

Netto hmotnosť	3,26 kg
----------------	---------

Brutto hmotnosť	3,66 kg
-----------------	---------

Číslo colnej sadzby	85044087
---------------------	----------

ETIM 9	EC000855
--------	----------

ETIM 8	EC000855
--------	----------

ECLASS 8.0	27189269
------------	----------

Popis výrobku	Invertory
---------------	-----------

Approvals

Explanations

Manufacturer's declaration